

❶ INSTALLATION



❷ INTERFACE CONNECTOR



Note: Connector interface is subject to model's specifications

English

Quick Start

❶ INSTALLATION

1. Power Cord (*)
2. VGA Cable (*)
3. Composite Video Cable
4. RS232 Cable
5. S-Video Cable
6. Audio Cable Jack/Jack
7. Audio Cable Jack/RCA
8. USB Cable (*)

Note: Connector interface is subject to model's specifications

Note: "(*)" Only for X1161N series.

❷ INTERFACE CONNECTOR

Connecting to a Computer

1. Ensure the projector and your computer are turned off.
2. Connect one end of the VGA cable to the "VGA IN" connector on the projector; connect the other end to the VGA connector on the computer and tighten the screws.
3. Connect one end of the power cord into the AC power socket on the projector; connect the other end to an electrical outlet.

Powering On the Projector

1. Remove the lens cap.
2. Turn on the projector first and then the computer.
3. Adjust the position, focus and zoom.
4. Run you presentation.

Powering Off the Projector

1. Press the power button twice.
2. Do not remove AC power cord from outlet until the projector fan shut down.

日本語

クィックスタート

❶ 接続見本

1. 電源コード (*)
2. VGA ケーブル (*)
3. コンポジットビデオケーブル
4. RS232 ケーブル
5. S-Video ケーブル
6. オーディオケーブルジャック/ジャック
7. オーディオケーブルジャック/RCA
8. USB ケーブル (*)

注意：コネクタインターフェイスは、モデルの仕様によって異なります

注意："(*)" X1161N シリーズ専用

❷ インターフェース（接続端子）

コンピュータとの接続

1. プロジェクタとコンピュータがオフになっていることを確認します。
2. VGA ケーブルをプロジェクタの「VGA IN」コネクタに指し込みます。次にD-SUBケーブルをコンピュータのVGA コネクタに指し込み、ネジをしっかりと締めます。
3. 電源コードをプロジェクタのAC電源ソケットに指し込み、もう片方をコンセントに指し込みます。

プロジェクタの電源を入れる

1. レンズキャップを外します。
2. 先にプロジェクタの電源をオンにしてから、コンピュータをオンにします。
3. 位置、フォーカス、ズームを調整します。
4. プレゼンテーションを開始します。

プロジェクタの電源を切る

1. 電源ホタンを2回押します。
2. プロジェクタのファンが止まるまで、AC電源コードはコンセントにつないだままにしておいてください。